

Note: Site cut edges to be primed

jhl_sttm_u_032

DRAINED FLASHING JOINT AT EXTERNAL CORNER